

35 MacDonald Ave, Dartmouth, NS, B3B 1C6 Tel: 902 468 6696

Fax: 902 468 8843

Toll Free NS: 1 800 971 3888

Web: www.constructionsafetyns.ca

Safe Job Procedures

Name of Job: Confined Space Entry	•	Development Date: March 30th, 2011		Developed By: CSNS	
Possible Hazards Present					
Claustrophobia Potential acute or	Flammable gases	Inhalation of fu vapors	mes or	water	
Pressurized liquids/gases	Restricted access/egress	chronic health hazards Asphyxiation		Physical Hazards (dust, light and noise)	
Personal Protective Equipment (PPE) and Devices Recommended					
Steel Toed Boots Detector/Gas monitor	Eye protection	Hand protectio	n	Fall arrest and quick retrieval	
Communication device	Self Contained Breathing Apparatus (SCBA)	go come come and and and and any and	me mur einer e	r man	

What is a proper safe job procedure to follow?

- Ensure confined space rescue team is contacted and on site
- Inspect the area for hazards and designate a leader
- Test confined space for the following:
 - Flammable or explosive material
 - Combustible gasses using a detector

Please note: This document is for information purposes only as a guide. The safe job procedures (SJP) and safe work practices (SWP) created for your workplace should reflect your organizations processes, equipment and hazards as identified by a hazard analysis. Construction Safety Nova Scotia does not assume responsibility for the use of information in this document. If assistance is needed to complete a SWP and SJP for your organization please contact CSNS member services at constructionsafetyns.ca or 1.800.971.3888.



35 MacDonald Ave, Dartmouth, NS, B3B 1C6 Tel: 902 468 6696

Fax: 902 468 8843

Toll Free NS: 1 800 971 3888

Web: www.constructionsafetyns.ca

- Adequate natural ventilation and/or install explosion proof fans and ducts. If ventilation is still poor, breathing apparatus or air line respirator may be required.
- Check confined space for toxic or corrosive materials. If detected, empty confined space and flush with pressurized water. All workers must wear respirator and eye protection if corrosive materials are present.
- Check equipment to be used and general conditions of the space, including:
 - o Disconnect, blind or lock entry ways that may allow hazardous materials in
 - Verify alarm devices indicating the presence of gas or oxygen deficiency are working
- Determine the area is safe, all workers understand the procedures, proper signage and barricades are used, and that all workers are knowledgeable of the rescue plan in the event of an emergency.

Please note: This document is for information purposes only as a guide. The safe job procedures (SJP) and safe work practices (SWP) created for your workplace should reflect your organizations processes, equipment and hazards as identified by a hazard analysis. Construction Safety Nova Scotia does not assume responsibility for the use of information in this document. If assistance is needed to complete a SWP and SJP for your organization please contact CSNS member services at constructionsafetyns.ca or 1.800.971.3888.